


**Template for generator side piece**

to cut out circle, use sharp knife, punch through each corrugation tanget to circle, working carefully around circumference. Then make second cut more deeply. Turn over and repeat punching operation, then cut free.

Alternative- purchase a compass cutter and use it to make the initial surface cuts, then cut through corrugations with knife.